COUNTY.

ELECTRICAL SAFETY INSPECTION REPORT FORM

Inspection Firm or Individual Name: George Ak	ouri	
Address: 4651 Sheridan Street Suite 26	0 Hollywood FL 33021	
Telephone Number: 954-292-7314		PULES AND
Inspection Commenced Date: 5/30/2025	Inspection Completed Date	5/30/2025
	are Required as Outlined in the Attac	
Florida Licensed Professional: Engineer	Architect	ORGE ANOUNT
Name: George Akouri		No. 49526 ★ =
License Number: 49526		The state of the s
	This item has been digitally signed and sealed by George Akouri on the date adjacent to the seal. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.	STATE OF CORIDA CONTROL OF CONTRO
I am qualified to practice in the discipline in which I am	,	
George Akouri George Akouri		
Signature: 2025.07.08 10:08:2	5-04'00' Date:	
This report has been based upon the minimum inspection guid of Rules and Appeals Policy #05-05. To the best of my knowled condition of the structure based upon careful evaluation of ob-	edge and ability, this report represents an	accurate appraisal of the present
1. DESCRIPTION OF STRUCTURE		
a. Name on Title: Las Vistas in Inverrary Co	ndominium Association Inc	c. (Reference)
b. Street Address: 3541 Inverrary Dr., Laude		
c. Legal Description: LAS VISTAS G IN INVERRAR		
d. Owner's Name: Las Vistas in Inverrary Co	ondominium Association Inc	c. (Reference)
e. Owner's Mailing Address: 3533 Inverrary Driv		
f. Email Address: accounting@lasvistascon		
g. Folio Number of Property on which Building is Located:	4941 23 CH 0010 (referen	ce)
h. Building Code Occupancy Classification: R	·	
i. Present Use: Condominum		
j. General Description: Three story concrete t	Duilding Type of Construction:	
k. Square Footage: Apprx. 25.332 S.F.	Number of Stories: 3	

I. Special Features:
None observed
m. Additional Comments:
The building is electrically safe for its intended use and occupancy. There are four (4) main disconnects.
#1, #2 - 800A, 120/240V, 1Ph breaker, each;
#3 - 200A, 120/240V, 1Ph breaker; #4 - 100A, 120/240V, 1Ph fuse;
#4 - 100A, 120/240V, 1F11 luse,
2. INSPECTIONS
a. Date of Notice of Required Inspection: Unknown
b. Date(s) of Actual Inspection: 5/30/2025
c. Name and Qualifications of Individual Preparing Report:
George Akouri, P.E.
d. Are any Electrical Repairs Required?
1. No – None Required
2. Yes – Required (Describe Nature of Repairs):
*** NOTE: Provide photographs as necessary to reflect relevant conditions and index appropriately. ***
3. ELECTRIC SERVICE
a. Size: Voltage (120/240); Amperage (800,200,100);
b. Main Service Protection (800,200,100 Amps): Fuse Breaker

c. Service Rating Amperage (800,200,100 Amps):
d. Phase: Three Phase Single Phase
e. Condition: Good Needs Repairs
Describe the Nature of Repairs:
4. SERVICE EQUIPMENT
a. Clearances: Good Requires Repair
Describe the Nature of Repairs:
5. ELECTRIC ROOMS
a. Clearances: Good Requires Repair
Describe the Nature of Repairs:

8. BRANCH CIRCUITS
a. Identified: b. Conductors: Good Deteriorated Must Be Identified Must Be Replaced Must Be Replaced
9. GROUNDING OF SERVICE
Good Repairs Required Comments:
10. GROUNDING OF EQUIPMENT
Good Repairs Required
Comments:

11. SERVICE CONDUITS/RACEWAYS
Good Repairs Required
Comments:
12. SERVICE CONDUCTOR AND CABLES
Good Repairs Required
Comments:
13. GENERAL CONDUIT/RACEWAYS
Good Repairs Required
Comments:

14. FEEDER CONDUCTORS
Good Repairs Required
Comments:
15. BUSWAYS
a. Location: Good Repairs Required
Describe the Nature of Repairs:
There are no busways. Not applicable.
16. OTHER CONDUCTORS
Good Repairs Required
Comments:
17. EMERGENCY LIGHTING
Good Repairs Required
Comments:

18. BUILDING EGRESS ILLUMINATION
Good Repairs Required
Comments:
19. FIRE ALARM SYSTEM
Good Repairs Required
Comments:
20. SMOKE DETECTORS
20. SMORE DETECTORS
Good Repairs Required
Comments:
Comments:
Comments:
Comments: 21. EXIT LIGHTS
Comments: 21. EXIT LIGHTS Good Repairs Required
Comments: 21. EXIT LIGHTS Good Repairs Required

22. EMERGENCY POWER SYSTEMS
Good Repairs Required
Comments:
There is no generator on site.
23. WIRING AND CONDUIT AT ALL PARKING LOTS AND GARAGES
Good Repairs Required
Comments:
24. SWIMMING POOL WIRING
Good Repairs Required
Comments:
25. WIRING TO MECHANICAL EQUIPMENT
Good Repairs Required
Comments:



AKOURI CONSULTING ENGINEERS

June 17, 2025

Name of title:

Las Vistas in Inverrary Condominium Association Inc. (Reference)

Address:

3541 INVERRARY DRIVE, LAUDERHILL FL 33319

Folio #:

4941 23 CH 0010 (Reference)

Legal Description:

LAS VISTAS G IN INVERRARY CONDO UNIT 101 PER CDO BK/PG: 5956/267(reference)

Reference:

Photos required for the 25/30-year recertification report.



2. Building photographs.






West elevation



South elevation



North elevation





Page 2 of 6


3. Electrical photographs.

Electrical room.











Grounding service.



Conduits.




Emergency Lighting/Exit Lights.



Smoke Detector.







If you have any questions or require additional information, please do not hesitate to contact this office at (954) 292-7314.



Sincerely

Professional Engineer Certified General Contractor Certified Roofing Contractor

PE# 0049526 CGC058841

CCC1329062

This item has been digitally signed and sealed by George Akouri on the date adjacent to the seal. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.