#### ELECTRICAL SAFETY INSPECTION REPORT FORM

COUNTY,
Inspection Firm or Individual Name: George Akouri
Address: 4651 Sheridan Street Suite 260 Hollywood FL 33021
Telephone Number: 954-292-7314
Inspection Commenced Date: 5/30/2025 Inspection Completed Date: 5/30/2025
inspection commenced bate inspection commenced bate.
No Repairs Required Repairs are Required as Outlined in the Attached Inspection Report
Florida Licensed Professional:  Engineer  Architect  No. 49526
Name: George Akouri
10500
This item has been digitally signed and sealed by George Akouri on the date adjacent to the seal.  Printed copies of this document are not considered signed and sealed and the signature part for the signature of the signature o
Seal
I am qualified to practice in the discipline in which I am hereby signing,
Signature: George Akouri George Akouri 2025.07.08 10:14:47 -04'00' Date: 6/11/2025
This report has been based upon the minimum inspection guidelines for building safety inspection as listed in the Broward County Board of Rules and Appeals Policy #05-05. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the structure based upon careful evaluation of observed conditions to the extent reasonably possible.
1. DESCRIPTION OF STRUCTURE
a. Name on Title: Las Vistas in Inverrary Condominium Association Inc. (Reference)
b. Street Address: 3776 Inverrary Blvd., Lauderhill, FL 33319 (Building R)
c. Legal Description: LAS VISTAS P-R IN INVERRARY CONDO UNIT 101 BLDG R PER CDO BK/PG: 5686/350(reference)
d. Owner's Name: Las Vistas in Inverrary Condominium Association Inc. (Reference)
e. Owner's Mailing Address: 3533 Inverrary Drive Lauderhill, FL 33319 (Reference)
f. Email Address: accounting@lasvistascondo.com Contact Number: (954) 731-8484
g. Folio Number of Property on which Building is Located: 4941 23 DD 0010 (reference)
h. Building Code Occupancy Classification: R
i. Present Use: Condominum
j. General Description: Four story concrete building Type of Construction:
k. Square Footage: Apprx. 37,392 S.F. Number of Stories: 4

I. Special Features: None observed
m. Additional Comments:
The building is electrically safe for its intended use and occupancy.
There are four (4) main disconnects. #1, #2 - 1000A, 120/240V, 1Ph breaker, each;
#3 - 225A, 120/240V, 1Ph breaker; #4 - 100A, 120/240V, 1Ph fuse;
2. INSPECTIONS
a. Date of Notice of Required Inspection: Unknown
b. Date(s) of Actual Inspection: 5/30/2025
c. Name and Qualifications of Individual Preparing Report:
George Akouri, P.E.
d. Are any Electrical Repairs Required?
1. No – None Required
2. Yes – Required (Describe Nature of Repairs):
*** NOTE: Provide photographs as necessary to reflect relevant conditions and index appropriately. ***
3. ELECTRIC SERVICE
a. Size: Voltage ( 120/240 ); Amperage ( 1000,225,100 );
b. Main Service Protection ( 1000,225,100 Amps): Fuse Breaker

E	
	c. Service Rating Amperage ( 1000,225,100 Amps):
	d. Phase: Three Phase Single Phase
	e. Condition: Good Needs Repairs
	Describe the Nature of Repairs:
	4. SERVICE EQUIPMENT
	a. Clearances: Good Requires Repair
	Describe the Nature of Repairs:
	5. ELECTRIC ROOMS
	a. Clearances: Good Requires Repair
	a. Clearances: Good Requires Repair
	Describe the Nature of Repairs:
- 1	

6. GUTTERS, WIREWAYS, ETC.
a. Location: Good Requires Repair
Describe the Nature of Repairs:
b. Taps and Box Fill: Good Requires Repair
Describe the Nature of Repairs:
7. ELECTRICAL SWITCHGEAR
a. Panel# (1) Good Needs Repairs
b. Panel# (2) Good Needs Repairs
c. Panel # (3) Good Needs Repairs
d. Panel # (4) Good Needs Repairs
e. Panel # ( ) Good Needs Repairs
Describe the Nature of Repairs:

8. BRANCH CIRCUITS
a. Identified:  b. Conductors:  Good  Deteriorated  Must Be Identified  Must Be Replaced  Describe the Nature of Repairs:
9. GROUNDING OF SERVICE
Good Repairs Required  Comments:
10. GROUNDING OF EQUIPMENT
Good Repairs Required
Comments:

11. SERVICE CONDUITS/RACEWAYS
Good Repairs Required
Comments:
12. SERVICE CONDUCTOR AND CABLES
Good Repairs Required
Comments:
13. GENERAL CONDUIT/RACEWAYS
Good Repairs Required
Comments:

14. FEEDER CONDUCTORS
Good Repairs Required
Comments:
15. BUSWAYS
TO. BOOWATO
a. Location: Good Repairs Required
Describe the Nature of Repairs:
There are no busways. Not applicable.
16. OTHER CONDUCTORS
Good Repairs Required
Comments:
17. EMERGENCY LIGHTING
17. EMERGENCY LIGHTING
Good Repairs Required
Comments:

18. BUILDING EGRESS ILLUMINATION		
Good Repairs Required		
Comments:		
19. FIRE ALARM SYSTEM		
Good Repairs Required		
Comments:		
20. SMOKE DETECTORS		
Good Repairs Required		
Comments:		
21. EXIT LIGHTS		
Good Repairs Required		
Comments:		

22. EMERGENCY POWER SYSTEMS
Good Repairs Required
Comments:
There is no generator on site.
23. WIRING AND CONDUIT AT ALL PARKING LOTS AND GARAGES
Good Repairs Required
Comments:
Comments.
24. SWIMMING POOL WIRING
Good Repairs Required
Comments:
25. WIRING TO MECHANICAL EQUIPMENT
Good Repairs Required
Comments:
Comments.



# AKOURI CONSULTING ENGINEERS

#### June 17, 2025

Name of title:

Las Vistas in Inverrary Condominium Association Inc. (Reference)

Address:

3776 Inverrary Blvd., Lauderhill, FL 33319 (Building P)

Folio #:

4941 23 DD 0010 (Reference)


Legal Description:

LAS VISTAS P-R IN INVERRARY CONDO UNIT 101 BLDG R PER CDO BK/PG:

5686/350(reference)

Reference:

Photos required for the 25/30-year recertification report.



Page 1 of 7

# 2. Building photographs.

### West elevation




East elevation



South elevation








# 3. Electrical photographs.

### Electrical room.











Grounding service, conduits.



Emergency Lighting/Exit Lights.



Smoke Detector.



Fire Alarm.



If you have any questions or require additional information, please do not hesitate to contact this office at (954) 292-7314.



Sincerely

## Akouri Consulting Engineers George Akouri, MSCE, P.E.

Professional Engineer PE# 0049526
Certified General Contractor CGC058841
Certified Roofing Contractor CCC1329062

This item has been digitally signed and sealed by George Akouri on the date adjacent to the seal. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.